

## **SAFETY RECALL** Santorini Metal Stacking Chair



Rear seat weld location



Select Santorini Metal Stacking Chairs have been recalled. To identify if your chair is part of this recall please follow these steps:

1) Turn the chair upside down.

2) Locate the underside seat base weld.

3) If the weld joint is located in the rear of the chair, your chair is not involved in the recall.

4) If the weld joint is located on the side of the chair, your chair is included in this recall.

## For a full refund, return the chair to any Cost Plus World Market store.

Call Cost Plus Inc. for additional information at

## 1-877-967-5362 7:00 am to 12:00 am EST

Further details are located at: www.worldmarket.com

In Cooperation with the U.S. Consumer Product Safety Commission